Qtv:

5 Um:

Each

5

: STEP WELDMENT

: D2563

: N/A

: C

- D2563 REV C

: 30/09/2008

Date:

Friday, 05/09/2008 10:07:48 AM

User:

Julie Lecocq

Process Sheet

Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Customer

: CU-DAR001 Dart Helicopters Services

Job Number **Estimate Number** : 41856A

P.O. Number

: 10176

This Issue

: 05/09/2008 : NC

Prsht Rev.

First Issue **Previous Run** : //

: 41115A

Written By Checked & Approved By

Comment

Type

S.O. No. :

: Est Rev:G 02.07.31 Re-format Location RF

: LARGE FAB ASSY

Additional Product

Job Number:

Seq. #:

Machine Or Operation:

Description:

1.0 D2244116

Step Extrusion

Comment: Qty.:

Comment: Qtv.:

1.0000 Each(s)/Unit

Total: 5.0000 Each(s)

Pick:

Step Extrusion B 33 733 (7)

Batch: 1/2 3 8023

End Plate

2.0

2.0000 Each(s)/Unit

Total:

10.0000 Each(s)

Pick:

Qty

Part No.

Description

Batch 335887

D2673-34 End Cap

3.0

D2561

Comment: Qty.:

2.0000 Each(s)/Unit Total:

10.0000 Each(s)

Pick:

Qty

Part No.

Description

D2561

Lug Plate

4.0

D2564

2.0000 Each(s)/Unit Total:

10.0000 Each(s)

Pick:

Qty

Part No.

Description

D2564

Mounting Angle

Comment: Qty.:

Batch 740936

Dart Aerospa	ace Ltd
--------------	---------

Dart Ae	rospace	e Lia		·								
W/O:		WORK ORDER CHANGES										
DATE STEE		PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
		-			ı							
							16-8131 W			,		
Part No:		PAR #:	: Fault Category:			NCR: Yes No DQA: Date:						
Resolution:			Disposition	on:	QA: N/C Closed: Date:							
NCR:		Wo	ORK ORD	ER NON-CONFORMA	ANCE	(NCR)					
	STEP	Description of NC	Corrective Action Secti		ion B		Verification		Approval	Approval		
DATE		Section A	Initial Chief Eng	Action Description Chief Eng	ī	Sign & Date	n & Section C	Chief Eng	QC Inspector			
						·						
	-				i							

NOTE: Date & initial all entries

Date: Friday, 05/09/2008 10:07:48 AM User: ا Julie Lecoca **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: STEP WELDMENT Job Number: 41856A Part Number: D2563 Job Number: ~Seq. #: **Machine Or Operation:** Description: 5.0 LARGE FAB 1 LARGE FABRICATION RESOURCE 1 **Comment: LARGE FABRICATION RESOURCE 1** SAD 08-12-19 1-Cut D2244 to 89.70" at 34 deg as per dwg D2563 SAD 08-12-19 2-Deburr ends 3-Weld (1 END CAP, LUG PLATES & MOUNTING ANGLE) as per dwg D2563 using DT 8343 A/R AL ROD Batch: <u>M/09560</u> <u>M108037</u> 4- Grind 6.0 QC9 VISUAL WELDING INSPECTION Comment: VISUAL WELDING INSPECTION 08-12-22 7.0 QC5 INSPECT WORK TO CUBRENT STEP Comment: INSPECT WORK TO CURRENT STEP 8.0 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 5 Chemical Conversion Coat as per QSI 005 4.1 9.0 QC3 INSPECT POWDER COAT/CHEMICAL CONVERSIO Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 10.0 LARGE FABRICATION RESOURCE 1 **Comment: LARGE FABRICATION RESOURCE 1** P2 08.12.29 5 P2 08.12.29 5 P2 08.12.29 5 1-Inspect for foreign object per QSI 024 2-Weld Remainig End as per Dwg D2563 using DT 8343 AL ROD 3-Grind

Dart Aerospace Lt	d
-------------------	---

W/O:			WORK ORDER CHANGES									
DATE	STEP	PROCEDURE CHANGE				Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto		
				∵# .								
Part No: PAR #:			· ····			No DQ						

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC		Verification	Annuaral					
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector		
•										
								}		
				• • • • • • • • • • • • • • • • • • •						

NOTE: Date & initial all entries

	ay, 05/09/2008 10:07:48 AM	
>	e Lecocq	Process Sheet
Customer:	CU-DAR001 Dart Helicopters Services	Drawing Name: STEP WELDMENT
Job Number:	41856Δ	D
Job Number:		Part Number: D2563
Seq. #:	Machine Or Operation:	Description
11.0	QC9	Description : VISUAL WELDING INSPECTION
Commi	ent: VISUAL WELDING INSPECTION	
12.0	QC5	INSPECT WORK TO CURRENT STEP
0		/68.12.29
13.0	ent: INSPECT WORK TO CURRENT ST POWDER COATING	POWDER COATING
70.0		E 1
		V109996
Comm	ent: POWDER COATING Touch up Alodine then	1 08/12/24 aludine (SX)
	Powder Coat White Gloss (Ref. 4.3.	
	11	200
	START TIME: OVEN TEMPERATURE: 32	30F
·	FINISH TIME:	30 M-1 08/12/30
14.0	HAND FINISHING1	HAND FINISHING RESOURCE #1
		m/09219 (5)
Commo	ent: HAND FINISHING RESOURCE #1	
	Wing Walk as per Dwg D2563 and C	QSI 005 4.4
15.0	QC3	INSPECT POWDER COAT/CHEMICAL CONVERSION
Commo	ent: INSPECT POWDER COAT/CHEMIC	CAL CONVERSION 9/1/6
16.0	QC21	FINAL INSPECTION/W/O RELEASE
Commo	ent: FINAL INSPECTION/W/O RELEASE	1 08/01/09
Job Completion		MF 09-01-
voo vompiction		- 774 07 01

Dart Aerospace Ltd

D 411110	Johada	2.4								
W/O:			WO	RK ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CHAN	CEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					1					
Part No:		PAR #:	Fault Categ	ory:	NCR: Y	es N	o DQ	A:	Date: _	J
Resolution:			Disposition: QA: N/C Closed: Date:						<u> </u>	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (N	CR)				
D. T.	STEP Description of NC Section A	Description of NC		n B		Verification		Approval	Approval	
DATE			Initial Chief Eng	Action Description Chief Eng		gn & ate	Section C		Chief Eng	QC Inspector
•										
							;			
I	1		1		1		1		1	1

NOTE: Date & initial all entries

